


View of the port engine room vent pipe of the J. W. WESTCOTT II. This view is from inside the pilothouse, through the port side cargo door. Photo taken on November 8, 2001.



View of the port engine room vent pipe taken from port deck aft of cargo door. The vent pipe was 2" in diameter, 14.5 inches high, and situated on the outboard side of the engine room. Photo taken on November 8, 2001.



Close up view of the one inch hole found at the base of the port engine room vent pipe on the J. W. WESTCOTT II. The hole leads directly into the engine room. Photo taken on November 8, 2001.